

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



24/09/2025 10:19:32
7°25'51"S 109°48'55"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 1+800
#Survei Jalan #DPUPR Kab Banjarnegara



24/09/2025 10:20:53
7°25'54"S 109°48'56"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 1+900
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



24/09/2025 10:22:23
7°25'57"S 109°48'56"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 2+000
#Survei Jalan #DPUPR Kab Banjarnegara



24/09/2025 10:23:36
7°26'0"S 109°48'55"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 2+100
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 2+510**

LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 2+700**

LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 2+900**

LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 3+100**

LOKASI : **STA 3+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 3+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 3+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 3+700**

LOKASI : **STA 3+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 3+900**

LOKASI : **STA 4+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



24/09/2025 10:51:39
7°26'44"S 109°49'6"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 4+100
#Survei Jalan #DPUPR Kab Banjarnegara



24/09/2025 10:52:37
7°26'46"S 109°49'9"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 4+200
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS 2	NAMA RUAS Randegan- Kalkuta	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 22
---------------	--------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



24/09/2025 10:53:39
7°26'46"S 109°49'12"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 4+300
#Survei Jalan #DPUPR Kab Banjarnegara



24/09/2025 10:54:39
7°26'49"S 109°49'13"E
Kabupaten Banjarnegara
#Ruas I.2 Randegan - Kalkuta
#STA 4+400
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS 2	NAMA RUAS Randegan- Kalkuta	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 23
---------------	--------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Randegan- Kalkuta



LOKASI : **STA 4+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+531**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
2	Randegan- Kalkuta		FIRDAUS & DAMAS	24

Rusak Berat
Rusak Ringan
Baik
Sedang