

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Jl KH. Acmad Dahlan**



LOKASI : **STA 0+000**

LOKASI : **STA 0+100**


KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 9.5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 9.5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
VI. 12	Jl KH. Acmad Dahlan		MELDA & DAHLAN	1

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Jl KH. Acmad Dahlan**



LOKASI : **STA 0+190**

LOKASI : **STA**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 9.5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN  
LEBAR PERKERASAN  
TYPE PERKERASAN

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
VI. 12	Jl KH. Acmad Dahlan		MELDA & DAHLAN	2