

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : JI Ki Jagapati II**



LOKASI : **STA 0+000**

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3.5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3.5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
VI. 25	Ji Ki Jagapati II		MELDA & DAHLAN	1

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : JI Ki Jagapati II**



LOKASI : **STA 0+200**

LOKASI : **STA 0+230**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3.5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3.5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
VI. 25	Ji Ki Jagapati II		MELDA & DAHLAN	2