

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jl Stadion



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

NO. RUAS VI. 31	NAMA RUAS Jl Stadion	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 1
--------------------	-------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jl Stadion



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

NO. RUAS VI. 31	NAMA RUAS Jl Stadion	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 2
--------------------	-------------------------	------------------------	-----------------------------------	--------------

