

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JI Selamanik



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS VI. 6	NAMA RUAS JI Selamanik	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 1
-------------------	---------------------------	------------------------	----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JI Selamanik



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+280**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS VI. 6	NAMA RUAS JI Selamanik	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 2
-------------------	---------------------------	------------------------	----------------------------------	--------------